


Work Hardening Curve for Fine Silver Sheet



CW (%)	HV	Condition
0	25	Annealed
10	49	1/4 hard
20	60	1/2 hard
30	72	3/4 hard
40	78	hard
50	84	Extra hard
60	84	Extra spring temper